




Highload Carrier Diagram and Part Numbers

Please use this diagram to help with identification of missing or replacement parts needed for the Carter Highload[®] carrier. A full listing of part numbers is given below:

Highload[®] MarkXII Yarn and Wire Carrier





Highload Carrier Parts List

Item	Component Part	Stock Number	Drawing Number
1	Flanged Bush for Top Bracket	410203	
2	Top Bracket	700026	
3	Top Swivel Catch	700086	
4	Spring Latch	700024	
5	Locking Catch	700068	
6	Weight Roller	700088	
7	Release Spring	700075	
8	Release Wire	700022	
9	Release Catch	700074	
10	Release Catch Stud	700073	
11	Nut for Release Catch Stud	420603	
12	Bush for Bobbin Spindle Support	410201	
13	Bobbin Spindle Support	700052	
14	Sliding Weight	700025	
15	Hardened Bush for Weight Roller	700054	
16	Top Swivel Catch Stud	700084	
17	Middle Roller	700070	
18	Hardened Bush for Middle Roller	700053	
19	Revolving Top Bush	700028	
20	Screw for Top Bracket	401441	
21	Retaining Collar	700079	
22	Garter Spring	700065	
23	Rubber Stop	700080	
24	Compression Spring	700056 - 700063	
25	Bobbin Spindle	700051	
26	Locking Catch Stud	700069	
27	Carrier Shoe & Rod Assembly	700023	
Notes:	Descriptions and designs given herein are not binding. Improvements are made from time to time and the right is reserved to modify specifications accordingly without notice. Many of the mechanisms and designs incorporated in the products of the company are covered by patents in the United Kingdom and elsewhere.		

Should you require assistance with parts identification for any Carter machinery, please do not hesitate to contact us.